Oil Field Environmental Incident Summary

Responsible Party: XTO ENERGY INC. **Well Operator:** XTO ENERGY INC.

Well Name: SASS 34X-8E

Field Name: HOFFLUND Well File #: 23008

Date Incident:7/6/2014Time Incident:04:25Facility ID Number:County:WILLIAMSTwp:154Rng:95Sec:8Qtr.

Location Description:

Submitted By: Shawn Dahl Received By:

Contact Person: Shawn Dahl

P.O Box 1589 Sidney, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No

Spilled Units Recovered Units Followup Units
50 Barrels 32 Barrels 32 barrels

Brine Other

Oil

Description of Other Released Contaminant:

Inspected: Written Report Received: 10/19/2015 Clean Up Concluded: 10/25/2014

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

none

Action Taken or Planned:

spill was contained in the metal berm, 3 BBLS leaked out but stayed on location.

Wastes Disposal Location: The recovered oil will be put back into production tanks, impacted soil

will be taken to PDI.

Agencies Involved:

Updates

Date: 7/7/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained on location within the diking according to the report. NDIC retains oversight.